
EXECUTIVE SUMMARY REPORT

Belleville Middle/High School

7/21/2017

What's New?

What a productive week it has been! Interior non-load bearing walls in the addition have been completed and the exterior brick veneer is underway! The walls in the secure entry and conference rooms have received their first coat of paint as well. Casework in these rooms will now be able to be installed this coming week giving the areas their new and improved look. Hayden Drive sits ready to be widened in the coming weeks and the asphalt paving will follow soon after. The foundation wall at the main entry was poured and backfilled in preparation for the new stairs to be poured next week! Our crews also started work in the Middle School classrooms and bathrooms by removing ceiling tile and replacing lighting fixtures. Stay tuned for more exciting updates in the weeks ahead!

The Past Week

- Poured foundation wall at main entry
- Skim coating in conference and secure entry
- Began laying new brick veneer on addition
- Completed interior non-load bearing walls on new addition
- Began painting in conference room and secure entry
- Demo ceilings and replacing light fixtures in Middle School

Coming Up in the Week Ahead

- Paint in conference room and secure entry
- Continue brick veneer on addition
- Fireproofing on addition
- Begin pouring curbs/sidewalks/stairs at main entry
- Install casework in conference room and secure entry



Shown above is a picture of a roller which was used to compact the newly excavated road coming off of Hayden Drive!



Did you know?

The oldest house paint was made of lime, which was mixed with milk and sometimes natural pigments. During this time paint could only be afforded by people of royalty or wealth. This dates all the way back to when King Tut's tomb was painted in 1324 B.C. The White House was also originally painted with a lime-based whitewash.

EXECUTIVE SUMMARY REPORT

Belleville Middle/High School

7/21/2017



Shown here is the soffit that will fall above the new casework in the secure entry area. Look at the fresh coat!



Shown to the left is a picture of the interior block that lays out the new bathrooms on the addition!



On the right we have a picture of the impressive formwork that was used to form the foundation walls at the new main entry feature for the High School!

